


Cutting dimension for both tube and folding stock adapters.



.625" (5/8")



First, cut here. It can help to cut long first and then sand down to .625"

After cutting you may need to sand this upper surface to get the adapter to fit flush. This is due to variations between models.